



## Guide of USB Cable drivers install


### 1. USB cable drivers is not install.




### 2. Click the USB cable drivers file CH341SER.exe




### 3. Click install button




### 4. Driver install finish



### 5. Recognize USB cable.



6. Run the software “PCLINK.exe”, and click the “Start” button



7. Software get the reading.

